## **Questions to Cabinet Re-Welshpool Schools Project**

## **Howell Drive Site for Ysgol Gymraeg y Trallwng**

- 1. Surely we have to look at a possible downscaling of the project to ensure it stays within budget. What other options have been looked at?
- 2. Were the developers given a free hand to produce a school which met the criteria set by Cadw without any thought on costs and if so why?
- **3.** And why weren't they asked to produce a new scheme encompassing the Cadw requirements BUT within the original budgets.

## Welshpool Church In Wales School - High School Site

While I support splitting the schemes to allow work to begin on Welshpool Church In Wales Primary School there are questions that need answering there too.

- 1. This report includes not a single word of explanation about the need for additional expenditure there just a brief mention of additional top soil replacement costs. What does that mean?
- 2. Neither does the report breakdown the level of costs but instead they are contained in an overall figure of £3.8million.

I received this response: "The estimates for the additional costs for a perfect site scenario is £770,000 (this includes exporting and importing gas membrane barriers works etc.

"Actual removal of the top soil is circa £176,000 which forms part of the overall required funding increase for Welshpool Church In Wales Primary School."

3. Why has this come to light so late in the day?

- 4. Why were proper searches not completed?
- 5. Who is responsible?
- 6. What actions are we taking as a council to investigate why these issues were not identified earlier?
- 7. Was anyone aware that the site for the new Church In Wales Primary School was originally used as a dumping ground when a large part of the town centre was raised to the ground for redevelopment in the late 50s or early 60s. If not why not?